Priority Areas Lead Testing and Corrective Actions September 2018 to December 2018 NS Guantanamo Bay Youth Center Building 2148

Table 1. Summary of Results

SAMPLING LOCATION DESCRIPTION			INITIA	L SAMPLING			AMPLING RESUL	rs	CORRECTIVE ACTIONS		POST REMEDIATION SAMPLING RESULTS	
CATEGORY Water Intended For:	SAMPLE ID	Outlet Description	First Draw (ppb)	Retest required?	Recomme Date Fixture Secured? (See Note 1)	winded Level = 20ppb Water Fountain 15 min. Follow up Flush Sample - Collected day before First Draw Sampling (ppb)	First Draw (ppb)	Follow up Flush - Collected 30 seconds after First Draw Sampling (ppb)	Description	First Draw (ppb) (See note 2)	mended Level = 20ppb Follow up Flush - Collected 30 seconds First Draw Samplin (ppb)	
SAMPLING DATE			9/15/2018			mm/dd/yyyy	10/22/2018	10/22/2018			mm/dd/yyyy	
RESULTS DATE			10/9/2018			mm/dd/yyyy	10/26/2018	10/26/2018			mm/dd/yyyy	
DRINKING	GTMO-2148-HALL-WFC-FD (BLDG 2148-8)	Fountain by Bathrooms - Cooler Fountain	1	No	N/A	N/A	N/A	N/A		N/A	N/A	
DRINKING	GTMO-2148-RM113-GYM- WFC-FD (BLDG 2148-9)	Fountain in Gym - Cooler Fountain	1.4	No	N/A	N/A	N/A	N/A		N/A	N/A	
COOKING	GTMO-2148-K-K-FD (BLDG 2148-10)	Kitchen - Kitchen Sink	8.1	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2148-RM125-RM-HHW- FD (BLDG 2148-1)	Staffing Area - High Handwash Sink	6.2	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2148-RM116-BATH- BOYS-HHWA-FD (BLDG 2148- 2)	Boys Bathroom - High handwash sink	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2148-RM116-BATH- BOYS-HHWB-FD (BLDG 2148- 3)	Boys Bathroom - High handwash sink	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2148-RM116-BATH- BOYS-HHWC-FD (BLDG 2148- 4)	Boys Bathroom - High handwash sink	Non Detect	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2148-RM118-BATH- GIRLS-HHWA-FD (BLDG 2148- 5)	Girls Bathroom - High handwash sink	0.78	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2148-RM118-BATH- GIRLS-HHWB-FD (BLDG 2148- 6)	Girls Bathroom - High handwash sink	1	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	GTMO-2148-RM118-BATH- GIRLS-HHWC-FD (BLDG 2148- 7)	Girls Bathroom - High handwash sink	1.1	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	· · · · · · · · · · · · · · · · · · ·	Hose outlet in rear of building Hose attachment	2.8	No	N/A	N/A	N/A	N/A		N/A	N/A	
WASHING	·	Hose outlet on parking lot side of building on left (facing building) - Hose attachment	35	Yes	10/12/2018	N/A	5.1	0.24	Fixture removed 12/10/18.	N/A	N/A	
WASHING	GTMO-2148-HOSED-FD (BLDG 2148-14)	Hose outlet on parking lot side of building on right (facing building) - Hose attachment	13	No	N/A	N/A	N/A	N/A		N/A	N/A	

Priority Areas Lead Testing and Corrective Actions September 2018 to December 2018 NS Guantanamo Bay Youth Center Building 2148

SAMPLING LOCATION DESCRIPTION			INITIAL SAMPLING RESULTS RE-SAMPLING RESULTS						CORRECTIVE ACTIONS	POST REMEDIATION SAMPLING RESULTS Recommended Level = 20ppb	
			Recommended Level = 20ppb								
CATEGORY	SAMPLE	Outlet Description	First Draw	Retest	Date Fixture	Water Fountain	First Draw	Follow up	Description	First Draw	Follow up Flush
Water Intended For:	ID		(ppb)	required?	Secured?	15 min. Follow up	(ppb)	Flush		(ppb)	- Collected 30 seconds after
					(See Note 1)	Flush Sample -		- Collected 30		(See note 2)	First Draw Sampling
						Collected day		seconds after			(ppb)
						before First Draw		First Draw			
						Sampling		Sampling			
						(ppb)		(ppb)			
SAMPLING DATE			9/15/2018			mm/dd/yyyy	10/22/2018	10/22/2018		mm/dd/yyyy	
RESULTS DATE			10/9/2018			mm/dd/yyyy	10/26/2018	10/26/2018			mm/dd/yyyy
WASHING	NSGB-2148-EXT-BATH-BOYS-	Boys Bathroom in Extension	0.73	No	N/A	N/A	N/A	N/A		N/A	N/A
	HHW-FD (BLDG 2148-15)	Area by Room 125 and Storage									
		Area , High Handwash sink									
WASHING	NSGB-2148-EXT-BATH-GIRLS-	Girls Bathroom in Extension	1.2	No	N/A	N/A	N/A	N/A		N/A	N/A
	HHW-FD (BLDG 2148-16)	Area by Room 125 and Storage									
		Area, High handwash sink									
[

Notos

Table 2. Summary Statistics

CATEGORY	INITIAL SAMPLING RESULTS		RE-SAMPLING RESULTS	POST REMEDIATION RESULTS					
	Recommended Level = 20ppb								
	First Draw (ppb)	Water Fountain Follow up Flush Sample -	First Draw (ppb)	Follow up Flush - Collected 30 seconds after	First Draw (ppb)				
		Collected day before First Draw Sampling (ppb)		First Draw Sampling (ppb)					
Total Drinking	2	0	0	0	0				
Total Drinking > 20 ppb	0	0	0	0	0				
Total Cook/Brush	1	0	0	0	0				
Total Cook/Brush > 20 ppb	0	0	0	0	0				
Total Washing	12	0	1	1	0				
Total Washing > 20 ppb	1	0	0	0	0				
Total Samples	15	0	1	1	0				
Total Samples > 20 ppb	1	0	0	0	0				

¹ Affected outlets were immediately secured after receiving verbal communication from the lab on results exceeding the recommended level of 20ppb.

² Post-remediation sampling was initially conducted on (DATE). Additional (ACTIONS) were implemented and final results below recommended level of 20 ppb for sample collected on (DATE) are shown on the table.